



# United States Department of the Interior

GEOLOGICAL SURVEY  
South Central Region  
P. O. Box 26124  
Albuquerque, New Mexico 87125

January 19, 1982

Mr. William Grey  
Chairman, Anaconda EIS Team  
The Anaconda Company  
555 17th Street  
Denver, Colorado 80217

Dear Mr. Grey:

The EIS Task Force has identified the following areas where our information on the Jackpile-Paguete Mine is inadequate. Please provide the following information as soon as possible:

1. The date that the Woodrow Mine was backfilled, a discussion of the type of material used for backfilling, and a discussion of the amount of settling that has or is occurring.
2. The date that Alpine and PW 2/3 were sealed, and a discussion of the method used to fill and seal these adits.
3. A map showing the extent of all underground mine workings and mine openings.
4. A map showing the location and description of all subsidence monitoring stations.

If you have any questions concerning this request, please contact Mr. David R. Sitzler at (505) 766-3830.

Sincerely yours,

(OPIG, SGD.) MARC E. NELSON  
Marc E. Nelson  
Task Force Leader

cc:  
Jackpile-Paguete Mine File  
PW 2/3 - Alpine File  
Woodrow Mine File  
D. R. Sitzler  
Chrono

MENelson:ab: 01-19-82